


National Transportation Safety Board

Natural Gas Pipeline Accident Manhattan, New York March 12, 2014





Manhattan, New York (Harlem)


- Consolidated Edison
- 8-inch cast iron/plastic distribution line (1890 / 2011)
- 8 in wc MAOP, 6 in wc operating
- 8 Fatalities
- 48 injuries









Utilities in the Accident Block





Saddle Fusion Joint Exemplar Test Piece








On-Scene Activities - Service Tee





Fusion Joint – Incomplete Fusion



Service Tee Fracture Face


- Radial band pattern (60%)
- Is incomplete fusion
- Is a weld defect
- Weak bond strength
- Caused by contamination or inadequate surface preparation before fusion welding



Service Tee – Crack at Outlet




- No evidence of pre-existing crack
- Rapid loading event from post-accident excavation





Gas

Main





2014 Sewer Main Damage





Conclusions

- Large hole in the sewer dated back to 2006
- Service tee to gas main weld not properly cleaned – lack of fusion
- Supporting soil under the plastic gas main washed into the damaged sewer for many months



Conclusions (cont'd)

- Gas leak resulted when sagging gas main opened the defective weld
- Post-accident excavation work
 - Separated the service tee from the main
 - Cracked the branch outlet
- Water main cracked after the explosion



Probable Cause

- Defective service tee fusion weld leaked gas, which migrated into the building and ignited
- Unrepaired sewer line breach allowed groundwater to undermine the supporting soil under the gas main and overstress the defective weld



Recommendations

- City of New York Improve sewer main integrity process
- Consolidated Edison Revise plastic pipe fusion procedure
 - Cleaning methods
 - Improve final visual inspection





National Transportation Safety Board

Robert J Hall Director Office of Railroad Pipeline and Hazardous Materials Investigations 202-314-6463 Robert.hall@ntsb.gov